ANK DATA SUMMARY AS OF 02/21/20

ST SITE INFORMATION

ITE ID: 2621

TE COMMENTS

SITE TAG #: A3619

EENY CONSTRUCTION COMPANY, INC.

545 RAINIER AVE S EATTLE, WA 98144

HONE #: (206) 722-0633

UBI: 578-075-168 001 0001

FACILITY SITE INFORMATION

**FACILITY SITE ID: 17754768** 

DEENY CONSTRUCTION COMPANY, INC.

2545 RAINIER AVE S SEATTLE, WA 98144

LATITUDE/LONGITUDE: 47° 34' 49.116"/ 122° 17 '58.812"

27/04 KS Steve Mack from Deeny says tanks 2,4 scrapped, tanks 1,3 (bigger tanks) riinsed but not filled with any material. Need SA reports.

Site Owner

Party ID: 1801

DEENY CONSTRUCTION COMPANY, INC.

TANK

2545 RAINIER AVE S

SEATTLE

(206) 722-0633

WA 98144

578075168

NK: 4. OIL

STATUS: Closure in Process STATUS DT: 8/6/1996

INSTALL DT: 11/15/1977 PERMIT EXPIRATION DT PERMANENTLY CLOSED DT

**UPGRADE DT:** 

**PIPING** 

2/29/2008

PUMP SYSTEM: Suction System Tank Chec

MATERIAL

CONSTRUCTION: Single Wall Tank

PRIMARY REL DETECT: Other

Single Wall Pipe

Other

SECOND REL DETECT: TIGHTNESS TEST:

ROSION PROTECTION: None

None

**OVERFILL PREVENT: None** 

CAPACITY RANGE: 111 TO 1,100 Gallons

COMPARTMENT #

SUBSTANCE STORED Used Oil/Waste Oil

SUBSTANCE USED

**ACTUAL CAPACITY** 

SPILL PREVENTION: None

Recycled (Used Oil)

ST SITE INFORMATION

SITE TAG # : A4577

RANK COLUCCIO CONSTRUCTION COMPANY

300 M L KING WAY S

EATTLE, WA 98118

HONE #: (206) 722-5306

UBI: 578-025-601 001 0001

FACILITY SITE INFORMATION

FACILITY SITE ID: 75459226

FRANK COLUCCIO CONSTRUCTION COMPANY

550

9600 MARTIN LUTHER KING JR WAY S

SEATTLE, WA 98118

LATITUDE/LONGITUDE: 47° 30' 56.45"/ 122° 16' 50.64"

TE COMMENTS

ITE ID: 2676

/9/98 AA- ISSUED TAG FROM NWRO. 12/7/98 TANKS MEET STANDARDS. CAJ\*\*\*\* 11/19/98 AA- OWNER MAILED HQ UPGRADE PERWORK 11/5/98; ALL TANKS UPGRADED. 4/14/98 SL--RE-ENTERED PRIME DATA, TANKS DO NOT MEET 1998 STANDARDS

Site Owner

Party ID: 2526

FRANK COLUCCIO CONSTRUCTION COMPANY

SEATTLE

WA 98118

(206) 722-5306

VK: LUG (6)

STATUS: Operational

**STATUS DT: 8/6/1996** 

INSTALL DT: 5/23/1973

578025601

2/29/2008

PERMIT EXPIRATION DT PERMANENTLY CLOSED DT

**UPGRADE DT: 2/19/1998** 

**PIPING** 

TANK

9600 M L KING WAY S

**Fiberglass** 

Double Wall Pipe

Automatic Line Leak Detection

SECOND REL DETECT:

TIGHTNESS TEST: ROSION PROTECTION: Impressed Current

CONSTRUCTION: Single Wall Tank

PRIMARY REL DETECT: Automatic Tank Gauging

MATERIAL: Steel

Annual

Corrosion Resistant

CAPACITY RANGE:30,000 to 49,999 Gallons **PUMP SYSTEM:** Pressurized System SPILL PREVENTION: Spill Bucket/Spill Box **OVERFILL PREVENT:** Ball Float Valve (vent line)

COMPARTMENT #

SUBSTANCE STORED

SUBSTANCE USED

**ACTUAL CAPACITY** 

Diesel

Machinery or Engine Lubricant

30000

Corrosion Resistant

SUBSTANCE USED

Motor Fuel for Vehicles

**ACTUAL CAPACITY** 

10000

SUBSTANCE STORED

Unleaded Gasoline

TIGHTNESS TEST:

ROSION PROTECTION: Impressed Current

**COMPARTMENT#** 

UST S **ANK DATA SUMMARY AS OF 02/21/20** ST SITE INFORMATION FACILITY SITE INFORMATION ITE ID: 2676 SITE TAG #: A4577 FACILITY SITE ID: 75459226 FRANK COLUCCIO CONSTRUCTION COMPANY RANK COLUCCIO CONSTRUCTION COMPANY 300 M L KING WAY S 9600 MARTIN LUTHER KING JR WAY S EATTLE, WA 98118 SEATTLE, WA 98118 HONE #: (206) 722-5306 LATITUDE/LONGITUDE: 47° 30' 56.45"/ 122° 16' 50.64" UBI: 578-025-601 001 0001 TE COMMENTS /9/98 AA- ISSUED TAG FROM NWRO. 12/7/98 TANKS MEET STANDARDS. CAJ\*\*\*\* 11/19/98 AA- OWNER MAILED HQ UPGRADE PERWORK 11/5/98; ALL TANKS UPGRADED. 4/14/98 SL--RE-ENTERED PRIME DATA, TANKS DO NOT MEET 1998 STANDARDS Site Owner Party ID: 2526 FRANK COLUCCIO CONSTRUCTION COMPANY SEATTLE (206) 722-5306 9600 M L KING WAY S WA 98118 578025601 PERMIT EXPIRATION DT PERMANENTLY CLOSED DT VK: LRG (5) STATUS: Operational INSTALL DT: 4/23/1973 STATUS DT: 8/6/1996 **UPGRADE DT: 2/19/1998** 2/29/2008 TANK **PIPING** MATERIAL: Steel Fiberglass CAPACITY RANGE:30,000 to 49,999 Gallons Double Wall Pipe **CONSTRUCTION:** Single Wall Tank PUMP SYSTEM: Pressurized System PRIMARY REL DETECT: Automatic Tank Gauging Automatic Line Leak Detection SPILL PREVENTION: Spill Bucket/Spill Box SECOND REL DETECT: OVERFILL PREVENT: Ball Float Valve (vent line) TIGHTNESS TEST: Annual ROSION PROTECTION: Impressed Current Corrosion Resistant COMPARTMENT # SUBSTANCE STORED SUBSTANCE USED **ACTUAL CAPACITY** Machinery or Engine Lubricant 30000 Diesel FACILITY SITE INFORMATION ST SITE INFORMATION ITE ID: 2725 SITE TAG #: A8109 FACILITY SITE ID: 94848477 HRIFTY CAR RENTAL THRIFTY CAR RENTAL 3836 PACIFIC HWY S 18836 PACIFIC HWY S SEATTLE, WA 98188 EATTLE, WA 98188 HONE #: (206) 870-9700 UBI: 601-064-644 001 0001 LATITUDE/LONGITUDE: 47° 27' 10.45"/ 122° 17' 49.79" TE COMMENTS 12/07 TD HQ CHANGED ADDRESS PER OWNER FROM 18836 PAC HWY TO INTERN'L BLVD.///10/07/04 KS operator said permatank per Lee Morse cords onsite. Site Owner PACIFIC NORTHWEST RENTAL AND LEASING, IN SEATTLE Party ID: 8946 (206) 870-9700 PO BOX 68370 601064644 VK: 1Z0528 STATUS: Operational INSTALL DT: 11/18/1998 PERMIT EXPIRATION DT PERMANENTLY CLOSED DT STATUS DT: 12/10/1999 **UPGRADE DT: 11/18/1998** 2/29/2008

**PIPING** 

SUBSTANCE USED

Motor Fuel for Vehicles

Automatic Line Leak Detection

Double Wall Pipe

Corrosion Resistant

No

SUBSTANCE STORED

Unleaded Gasoline

CAPACITY RANGE:

12000

PUMP SYSTEM: Pressurized System

OVERFILL PREVENT: Automatic Shutoff (fill pipe)

SPILL PREVENTION: Spill Bucket/Spill Box

**ACTUAL CAPACITY** 

TANK

MATERIAL: Steel Clad with Corrosion Resistant (Fiberglass

CONSTRUCTION: Double Wall Tank

PRIMARY REL DETECT: Automatic Tank Gauging

COMPARTMENT #

TIGHTNESS TEST: Not Performed

ROSION PROTECTION: Corrosion Resistant

SECOND REL DETECT:

SITE/TANK DATA SUMMARY AS OF 07

007

ST SITE INFORMATION

ITE ID: 2725

SITE TAG #: A8109

U

HRIFTY CAR RENTAL

3836 PACIFIC HWY S EATTLE, WA 98188

HONE #: (206) 870-9700

UBI: 601-064-644 001 0001

FACILITY SITE INFU. WATION

FACILITY SITE ID: 94848477

THRIFTY CAR RENTAL

18836 PACIFIC HWY S SEATTLE, WA 98188

LATITUDE/LONGITUDE: 47° 27' 10.45"/122° 17' 49.79"

TE COMMENTS

12/07 TD HQ CHANGED ADDRESS PER OWNER FROM 18836 PAC HWY TO INTERN'L BLVD.///10/07/04 KS operator said permatank per Lee Morse cords onsite.

Site Owner

2arty ID: 8946

PACIFIC NORTHWEST RENTAL AND LEASING, IN SEATTLE

PO BOX 68370

WA 98168

(206) 870-9700 601064644

VK: 1

STATUS: Removed

**STATUS DT: 8/6/1996** TANK

INSTALL DT: 1/1/1966 UPGRADE DT:

PIPING

PERMIT EXPIRATION DT PERMANENTLY CLOSED DT

2/29/2008

MATERIAL:

**CONSTRUCTION:** Single Wall Tank

Single Wall Pipe

PRIMARY REL DETECT: Statistical Inventory Reconciliation

Suction

None

SECOND REL DETECT: TIGHTNESS TEST:

ROSION PROTECTION: None

SUBSTANCE STORED

SUBSTANCE USED

**ACTUAL CAPACITY** 

SPILL PREVENTION: None

**OVERFILL PREVENT: None** 

CAPACITY RANGE: 2,001 to 4,999 Gallons

PUMP SYSTEM: Gravity Delivery System (N

COMPARTMENT #

Unleaded Gasoline

Motor Fuel for Vehicles

ST SITE INFORMATION

ITE ID: 2880

SITE TAG # : A3620

RIENDLY FOOD MART 127 FAUNTLEROY WAY SW

EATTLE, WA 98136

HONE #: (425) 228-1825

UBI: 601-619-994 001 0008

FACILITY SITE INFORMATION-

FACILITY SITE ID: 88254987

FRIENDLY FOOD MART

7427 FAUNTLEROY WAY SW

SEATTLE, WA 98136

LATITUDE/LONGITUDE: 47° 32' 11.51"/ 122° 23' 35.94"

TE COMMENTS

29/98 SS/TANKS MEET 1998 STANDARDS.

(3.12.98)

TA REQUESTED. SEE INSPECTIONS. SITE UPGRADED. MEETS '98 SPECS.

Site Owner

Party ID: 388487

FRIENDLY FUELS, INC.

1190 SUNSET BLVD NE STE F

RENTON

(425) 228-1825

WA 98056

601619994

NK: D. III

STATUS: Operational

INSTALL DT: 4/18/1987

PERMIT EXPIRATION DT PERMANENTLY CLOSED DT

STATUS DT: 8/6/1996

**UPGRADE DT: 12/5/1997** 

PIPING

2/29/2008

TANK

MATERIAL: Steel Clad with Corrosion Resistant (Flexible Piping

CONSTRUCTION: Single Wall Tank

Double Wall Pipe

PRIMARY REL DETECT: Automatic Tank Gauging

Automatic Line Leak Detection

SECOND REL DETECT:

TIGHTNESS TEST: Every 5 Years ROSION PROTECTION: Corrosion Resistant Annual

Corrosion Resistant

PUMP SYSTEM: Pressurized System SPILL PREVENTION: Spill Bucket/Spill Box **OVERFILL PREVENT: Overfill Alarm** 

CAPACITY RANGE: 2,001 to 4,999 Gallons

COMPARTMENT#

SUBSTANCE STORED

SUBSTANCE USED

**ACTUAL CAPACITY** 

Unleaded Gasoline

Motor Fuel for Vehicles

4000

# UST INS TION SUMMARY AS OF 02/21/20

ST SITE INFORMATION

ITE ID: 2676

SITE TAG #: A4577

RANK COLUCCIO CONSTRUCTION COMPANY

300 M L KING WAY S EATTLE, WA 98118

HONE #: (206) 722-5306

UBI: 578-025-601 001 0001

FACILITY SITE INFORMATION-

FACILITY SITE ID: 75459226

FRANK COLUCCIO CONSTRUCTION COMPANY

9600 MARTIN LUTHER KING JR WAY S

SEATTLE, WA 98118

LATITUDE/LONGITUDE: 47° 30' 56.45"/ 122° 16' 50.64"

TE COMMENTS-

9/98 AA- ISSUED TAG FROM NWRO. 12/7/98 TANKS MEET STANDARDS. CAJ\*\*\*\* 11/19/98 AA- OWNER MAILED HQ UPGRADE PAPERWORK 11/5/98; ALL TANKS GRADED. 4/14/98 SL--RE-ENTERED PRIME DATA, TANKS DO NOT MEET 1998 STANDARDS

## I' : GRATED SITE INFORMATION : EM US) INSPECTION SUMMARY AS OF 02/21/2007

ST SITE INFORMATION

ITE ID: 2621

SITE TAG #: A3619

EENY CONSTRUCTION COMPANY, INC.

545 RAINIER AVE S EATTLE, WA 98144

HONE #: (206) 722-0633

UBI: 578-075-168 001 0001

FACILITY SITE INFORMATION-

FACILITY SITE ID: 17754768

DEENY CONSTRUCTION CO INC

2545 RAINIER AVE S SEATTLE, WA 98144

LATITUDE/LONGITUDE: 47° 34' 49.116"/122° 17' 58.812"

#### TE COMMENTS-

5/04 KS Steve Mack shop foreman x229 \\\\JUL 1, 98 MIDAY\\ RE-ENTERED DATA FROM FILE AND TANK 5.COMPART MEETS 1998 STANDARDS\\\\4/8/98 KK SITE HAS T BEEN REGISTERED SINCE 1996. 4 TANKS HAVE BEEN EITHER CLOSED OR REMOVED. 1 NEW TANK INSTALLED, 10,000 COMPARTMENT, WITH 6,000 DIESEL AND 00 UNLEADED GAS. OWNER IS IN PROCESS OF REGISTERING TANK.

STING 123

### SPECTOR: KLOCKE, KAREN

SPECTION INFORMATION

INSPECTION TYPE: Technical Assistance

ISPECTION METHOD: Field Visit

**NSPECTION RESULT:** Followup Required

INSPECTION DATE: 4/8/1998
SPECTION CONTACT: STEVE MACK

SOC INSPECTION RESULTS-

SOC SPILL/OVERFILL/CORROSION: Not Evaluated SOC RELEASE DETECTION: Not Evaluated

#### SPECTION COMMENTS

TANKS REMOVED OR CLOSED IN PLACE IN 1992. HAD ENVIRO FIRM ON SITE, BUT O/O CUT UP AND DISPOSED OF TANKS HIMSELF. SITE NOT EGISTERED SINCE 1996. WRITING NOC TO DISTRIBUTOR, DELTA WESTERN, FOR DELIVERING TO NON-REGISTERED SITE.

## SPECTOR: KLOCKE, KAREN

SPECTION INFORMATION

INSPECTION TYPE: Technical Assistance

ISPECTION METHOD: Field Visit

NSPECTION RESULT: Followup Required

INSPECTION DATE: 4/8/1998
SPECTION CONTACT: STEVE MACK

SOC INSPECTION RESULTS

SOC SPILL/OVERFILL/CORROSION: Not Evaluated SOC RELEASE DETECTION: Not Evaluated

### ISPECTION COMMENTS

FANKS REMOVED OR CLOSED IN PLACE IN 1992. HAD ENVIRO FIRM ON SITE, BUT O/O CUT UP AND DISPOSED OF TANKS HIMSELF. SITE NOT EGISTERED SINCE 1996. WRITING NOC TO DISTRIBUTOR, DELTA WESTERN, FOR DELIVERING TO NON-REGISTERED SITE.